Instrument Schedule

How to Succeed in Business Without Really Trying

2/1/22

H2S-Marist.lw6

LD: Jeremy Johnson
ALD: Rachel Chalfin

TABLE OF CONTENTS

Cove 1
FOH BOOM L 3
FOH BOOM R 4
Apron 5
LX 1 7
LX 2 9
LX 3 11
LX1 TAILDOWN SL 12
LX2 TAILDOWN SL 12
LX3 TAILDOWN SL 13
LX1 TAILDOWN SR 13
LX2 TAILDOWN SR 13
LX3 TAILDOWN SR 14
Boom 1 SL 14
Boom 2 SL 14
Boom 3 SL 15
Boom 1 SR 15
Boom 2 SR 15
Boom 3 SR 15
Elevator Door SR 16
Elevator Door C 16
Elevator Door SL 16
Biggley's Desk 16
US Set 17
MS Set 17
LS-6 17
LS-11 18
Portal 1 SR 18
Portal 1 Header 18
Portal 1 SL 18
Portal 2 SR 19
Portal 2 Header 19
Portal 2 SL 19
House 19

LD: Jeremy Johnson
ALD: Rachel Chalfin

Instrument Schedule

How to Succeed in Business Without Really Trying

2/1/22
H2S-Marist.lw6

Cove

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	6x12 - 360Q	G365+R119	Front	750w	(1)	
2	6x12 - 360Q	G365+R119	Front	750w	(11)	
3	S4-19°	R119	Special	750w	(301)	
4	6x12 - 360Q	G365+R119	Front	750w	(2)	
5	S4-19°	R119	Special	750w	(302)	
6	6x12 - 360Q	G365+R119	Front	750w	(12)	
7	6x12 - 360Q	G365+R119	Front	750w	(3)	
8	6x12 - 360Q	G365+R119	Front	750w	(13)	
9	S4-19°	R119	Special	750w	(303)	
10	6x12 - 360Q	G365+R119	Front	750w	(4)	
11	6x16 - 360Q	G365+R119	Front	750w	(5)	
12	6x12 - 360Q	G365+R119	Front	750w	(14)	
13	6x12 - 360Q	G365+R119	Front	750w	(6)	
14	6x16 - 360Q	G365+R119	Front	750w	(7)	

Instrument Schedule

How to Succeed in Business Without Really Trying

Cove

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
15	6x12 - 360Q	G365+R119	Front	750w	(15)	
16	S4-19°	R119	Special	750w	(304)	
17	6x12 - 360Q	G365+R119	Front	750w	(16)	
18	6x12 - 360Q	G365+R119	Front	750w	(8)	
19	6x12 - 360Q	G365+R119	Front	750w	(17)	
20	S4-19°	R119	Special	750w	(305)	
21	6x12 - 360Q	G365+R119	Front	750w	(9)	
22	S4-19°	R119	Special	750w	(306)	
23	6x12 - 360Q	G365+R119	Front	750w	(18)	
24	6x12 - 360Q	G365+R119	Front	750w	(10)	

Instrument Schedule

How to Succeed in Business Without Really Trying

FOH BOOM L

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	S4-26°	R09+R119	Side WM	750w	(33)	
2	S4-36°	R09+R119	Side WM	750w	(34)	
3	S4-26°	R34+R119	Side Toner	750w	(31)	
4	S4-36°	R34+R119	Side Toner	750w	(32)	
5	S4-26°	L201+R119	Side CL	750w	(35)	
6	S4-36°	L201+R119	Side CL	750w	(36)	
7	S4-26°	R64	Side Temp	750w	(37)	

Instrument Schedule

How to Succeed in Business Without Really Trying

FOH BOOM R

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	S4-26°	R09+R119	Side WM	750w	(23)	
2	S4-36°	R09+R119	Side WM	750w	(24)	
3	S4-26°	R34+R119	Side Toner	750w	(21)	
4	S4-36°	R34+R119	Side Toner	750w	(22)	
5	S4-26°	L201+R119	Side CL	750w	(25)	
6	S4-36°	L201+R119	Side CL	750w	(26)	
7	S4-26°	R64	Side Temp	750w	(27)	

Instrument Schedule

How to Succeed in Business Without Really Trying

Apron

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	Cove MX	R104V	Uplight	45w	(251)	
2	Cove MX	R104V	Uplight	45w	(252)	
3	Cove MX	R104V	Uplight	45w	(253)	
4	Cove MX	R104V	Uplight	45w	(254)	
5	Cove MX	R104V	Uplight	45w	(255)	
6	Cove MX	R104V	Uplight	45w	(256)	
7	Cove MX	R104V	Uplight	45w	(257)	
8	Cove MX	R104V	Uplight	45w	(258)	
9	Cove MX	R104V	Uplight	45w	(259)	
10	Cove MX	R104V	Uplight	45w	(260)	
11	Cove MX	R104V	Uplight	45w	(261)	
12	Cove MX	R104V	Uplight	45w	(262)	
13	Cove MX	R104V	Uplight	45w	(263)	
14	Cove MX	R104V	Uplight	45w	(264)	
15	Cove MX	R104V	Uplight	45w	(265)	

Instrument Schedule

How to Succeed in Business Without Really Trying

Apron

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
16	Cove MX	R104V	Uplight	45w	(266)	
17	Cove MX	R104V	Uplight	45w	(267)	
18	Cove MX	R104V	Uplight	45w	(268)	
19	Cove MX	R104V	Uplight	45w	(269)	
20	Cove MX	R104V	Uplight	45w	(270)	
21	Cove MX	R104V	Uplight	45w	(271)	
22	Cove MX	R104V	Uplight	45w	(272)	
23	Cove MX	R104V	Uplight	45w	(273)	
24	Cove MX	R104V	Uplight	45w	(274)	

Instrument Schedule

How to Succeed in Business Without Really Trying

LX 1

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	S4-50°	R02, T:78545	Portal Temp	750w	(133)	
2	CS Par - No Lens	L250	Downlight	90w	(106)	4/31
3	VL-2500 Spot	N/C	Mover	700w	(203)	4/93
4	CS Par - No Lens	L250	Downlight	90w	(105)	4/25
5	S4-36°+12" SA	L201+R119+HS	Side CL	750w	(51)	
6	S4-36°	G365+R119	Front	750w	(19)	
7	Aura 19x15w+Concentric Rings	N/C	Mover	285w	(212)	4/140
8	CS Par - No Lens	L250	Downlight	90w	(104)	4/19
9	S4-36°	G365+R119	Front	750w	(19)	
10	VL-2500 Spot	N/C	Mover	700w	(202)	4/71
11	S4-36°	G365+R119	Front	750w	(20)	
12	CS Par - No Lens	L250	Downlight	90w	(103)	4/13
13	Aura 19x15w+Concentric Rings	N/C	Mover	285w	(211)	4/115
14	S4-36°	G365+R119	Front	750w	(20)	
15	S4-36°+12" SA	R3408+R119	Side WM	750w	(42)	

Instrument Schedule

How to Succeed in Business Without Really Trying

LX 1

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
16	CS Par - No Lens	L250	Downlight	90w	(102)	4/7
17	VL-2500 Spot	N/C	Mover	700w	(201)	4/49
18	CS Par - No Lens	L250	Downlight	90w	(101)	4/1
19	S4-36°+Donut 6.25"	R3408, T:78489	Warehouse Temp	750w	(175)	
20	S4-50°	R02, T:78545	Portal Temp	750w	(132)	
21	S4-50°	R02, T:78545	Portal Temp	750w	(131)	

Instrument Schedule

How to Succeed in Business Without Really Trying

LX 2

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	S4-50°	R02, T:78545	Portal Temp	750w	(136)	
2	CS Par - No Lens	L250	Downlight	90w	(112)	5/31
3	VL-2500 Spot	N/C	Mover	700w	(206)	5/93
4	S4-36°	R365+HS	Down Temp	750w	(123)	
5	CS Par - No Lens	L250	Downlight	90w	(111)	5/25
6	S4-36°+12" SA	L201+R119+HS	Side CL	750w	(53)	
7	S4-36°	R365+HS	Down Temp	750w	(122)	
8	CS Par - No Lens	L250	Downlight	90w	(110)	5/19
9	VL-2500 Spot	N/C	Mover	700w	(205)	5/71
10	CS Par - No Lens	L250	Downlight	90w	(109)	5/13
11	S4-36°	R365+HS	Down Temp	750w	(121)	
12	S4-36°+12" SA	R3408+R119	Side WM	750w	(44)	
13	CS Par - No Lens	L250	Downlight	90w	(108)	5/7
14	S4-36°	R365+HS	Down Temp	750w	(120)	
15	VL-2500 Spot	N/C	Mover	700w	(204)	5/49

Instrument Schedule

How to Succeed in Business Without Really Trying

LX 2

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
16	S4-36°+Donut 6.25"	R3204+HS, T:78486	Biggley Temp	750w	(177)	
17	CS Par - No Lens	L250	Downlight	90w	(107)	5/1
18	S4-50°	R02, T:78545	Portal Temp	750w	(135)	
19	S4-36°+Donut 6.25"	R3204+HS, T:78486	Biggley Temp	750w	(176)	
20	S4-50°	R02, T:78545	Portal Temp	750w	(134)	

Instrument Schedule

How to Succeed in Business Without Really Trying

LX 3

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	S4-50°	L201+HS, T:78496	Elevator Temp	750w	(80)	
2	CS CYC	N/C	Cityscape	133w	(194)	6/121
3	CS Par - No Lens	L250	Downlight	90w	(118)	6/31
4	VL-2500 Spot	N/C	Mover	700w	(208)	6/71
5	CS Par - No Lens	L250	Downlight	90w	(117)	6/25
6	CS CYC	N/C	Cityscape	133w	(193)	6/114
7	Aura 19x15w+Concentric Rings	N/C	Mover	285w	(224)	6/203
8	CS Par - No Lens	L250	Downlight	90w	(116)	6/19
9	Aura 19x15w+Concentric Rings	N/C	Mover	285w	(223)	6/178
10	CS CYC	N/C	Cityscape	133w	(192)	6/107
11	Aura 19x15w+Concentric Rings	N/C	Mover	285w	(222)	6/153
12	CS Par - No Lens	L250	Downlight	90w	(115)	6/13
13	Aura 19x15w+Concentric Rings	N/C	Mover	285w	(221)	6/128
14	CS CYC	N/C	Cityscape	133w	(191)	6/100
15	CS Par - No Lens	L250	Downlight	90w	(114)	6/7

Instrument Schedule

How to Succeed in Business Without Really Trying

LX 3

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
16	VL-2500 Spot	N/C	Mover	700w	(207)	6/49
17	CS Par - No Lens	L250	Downlight	90w	(113)	6/1
18	CS CYC	N/C	Cityscape	133w	(190)	6/93
19	S4-50°	L201+HS, T:78496	Elevator Temp	750w	(79)	

LX1 TAILDOWN SL

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	S4-36°+12" SA	L201+R119+HS	Side CL	750w	(52)	
2	S4-36°+Donut 6.25"	R3204+HS, T:G635	Side Temp	750w	(72)	
3	CS Par - No Lens+12" SA	L228	Side Toner	90w	(62)	4/43
4	Aura 19x15w+Concentric Rings	N/C	Mover	285w	(214)	4/190

LX2 TAILDOWN SL

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	S4-36°+12" SA	L201+R119+HS	Side CL	750w	(54)	
2	S4-36°+Donut 6.25"	R3204+HS, T:G635	Side Temp	750w	(74)	
3	CS Par - No Lens+12" SA	L228	Side Toner	90w	(64)	5/43

Instrument Schedule

How to Succeed in Business Without Really Trying

LX3 TAILDOWN SL

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	S4-36°+12" SA	L201+R119+HS	Side CL	750w	(56)	
2	S4-36°+Donut 6.25"	R3204+HS, T:G635	Side Temp	750w	(76)	
3	S4-50°+12" SA	R365+HS, T:78496	Elevator Temp	750w	(78)	
4	CS Par - No Lens+12" SA	L228	Side Toner	90w	(66)	6/43

LX1 TAILDOWN SR

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	S4-36°+12" SA	R3408+R119	Side WM	750w	(41)	
2	S4-36°+Donut 6.25"	R3408, T:G635	Side Temp	750w	(71)	
3	CS Par - No Lens+12" SA	L228	Side Toner	90w	(61)	4/37
4	Aura 19x15w+Concentric Rings	N/C	Mover	285w	(213)	4/165

LX2 TAILDOWN SR

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	S4-36°+12" SA	R3408+R119	Side WM	750w	(43)	
2	S4-36°+Donut 6.25"	R3408, T:G635	Side Temp	750w	(73)	
3	CS Par - No Lens+12" SA	L228	Side Toner	90w	(63)	5/37

Instrument Schedule

How to Succeed in Business Without Really Trying

LX3 TAILDOWN SR

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	S4-36°+12" SA	R3408+R119	Side WM	750w	(45)	
2	S4-36°+Donut 6.25"	R3408, T:G635	Side Temp	750w	(75)	
3	S4-50°+12" SA	R365+HS, T:78496	Elevator Temp	750w	(77)	
4	CS Par - No Lens+12" SA	L228	Side Toner	90w	(65)	6/37

Boom 1 SL

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	Colorado 1 Quad ZT	N/C	Side Toner	120w	(150)	8/61
2	Colorado 1 Quad ZT	N/C	Side Toner	120w	(151)	8/73

Boom 2 SL

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	Colorado 1 Quad ZT	N/C	Side Toner	120w	(152)	8/85
2	Colorado 1 Quad ZT	N/C	Side Toner	120w	(153)	8/97

Instrument Schedule

How to Succeed in Business Without Really Trying

Boom 3 SL

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	Colorado 1 Quad ZT	N/C	Side Toner	120w	(154)	8/109

Boom 1 SR

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	Colorado 1 Quad ZT	N/C	Side Toner	120w	(140)	8/1
2	Colorado 1 Quad ZT	N/C	Side Toner	120w	(141)	8/13

Boom 2 SR

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	Colorado 1 Quad ZT	N/C	Side Toner	120w	(142)	8/25
2	Colorado 1 Quad ZT	N/C	Side Toner	120w	(143)	8/37

Boom 3 SR

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	Colorado 1 Quad ZT	N/C	Side Toner	120w	(144)	8/49

Instrument Schedule

How to Succeed in Business Without Really Trying

Elevator Door SR

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
3	S4 ParNel	R02	Downlight	750w	(171)	

Elevator Door C

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
2	S4 ParNel	R02	Downlight	750w	(173)	
4	S4 ParNel+Floor Base	TBD	WM Back	750w	(174)	

Elevator Door SL

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	S4 ParNel	R02	Downlight	750w	(172)	

Biggley's Desk

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	Birdie	R65	TV Practical	75w	(182)	

Instrument Schedule

How to Succeed in Business Without Really Trying

US Set

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	Practical	N/C	WWW SIGN		(180)	
NA	2K Fresnel	N/C	TV Studio Rover	2kW	(181)	

MS Set

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	50-RGB Node String	N/C	Party Lights	150w	(601)	
2	50-RGB Node String	N/C	Party Lights	150w	(651)	
3	50-RGB Node String	N/C	Party Lights	150w	(701)	

LS-6

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	4' Daylight Tubes	N/C	Office Light		(280)	
2	4' Daylight Tubes	N/C	Office Light		(281)	
3	4' Daylight Tubes	N/C	Office Light		(282)	
4	4' Daylight Tubes	N/C	Office Light		(283)	

Instrument Schedule

How to Succeed in Business Without Really Trying

LS-11

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	4' Daylight Tubes	N/C	Office Light		(284)	
2	4' Daylight Tubes	N/C	Office Light		(285)	
3	4' Daylight Tubes	N/C	Office Light		(286)	

Portal 1 SR

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	RGBW LED Tape	N/C	Portal Outline	60w	(501)	8/121

Portal 1 Header

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	RGBW LED Tape	N/C	Portal Outline	60w	(502)	8/129

Portal 1 SL

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	RGBW LED Tape	N/C	Portal Outline	60w	(503)	8/137

Instrument Schedule

How to Succeed in Business Without Really Trying

Portal 2 SR

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	RGBW LED Tape	N/C	Portal Outline	60w	(504)	8/145

Portal 2 Header

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	RGBW LED Tape	N/C	Portal Outline	60w	(505)	8/153

Portal 2 SL

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	RGBW LED Tape	N/C	Portal Outline	60w	(506)	8/161

House

U#	Instrument Type & Accessory	Color & Gobo	Purpose	Load	Chan	Addr
1	Houselight	N/C	Houselights	100w	(800)	